
AFK well-control equipment




- 1. Manometer
- 2. Blind flange for manometer*
- 3. ZMS shutter
- 4. Crosspiece
- 5. Adjustable throttle valve*
- 6. Flange for welding
- 7. Adapter
- 8. Wellhead crosspiece
- 9. Blind flange for manometer*



- 1. Air valve
- 2. Adapter
- 3. Threading for pipe suspension
- 4. Sealing ring
- 5. Wellhead crosspiece
- 6. Air valve
- 7. Delivery valve

Standard diagrams of bradenheads for T-pieces and crosspiece fittings under GOST 13846-89



1- reducing taper elbow for the casing head; 2 – T-piece; 3 – shutoff device; 4 – manometer with a shutoff and discharge device; 5 – throttle valve; 6 – counter flange; 7 – crosspiece

Standard diagrams of piping (casing heads) for well-control equipment under GOST 13846-89



1- counter flange; 2 – shutoff device; 3 – crosspiece; 4 – manometer with a valve